

# WS-6000M



## Machine Specification

Voltage (Single Phrase)	100~120V AC 50/60HZ	220~240V AC 50/60HZ
Motor Rated Ampere	20A	10A
Motor Rated Power Consumption	2050W	
No-load Speed	High Speed 750rpm Dia. 13(1/2")~35mm(1-3/8")	
	Low Speed 450rpm Dia. 36(1-7/16")~60mm(2-3/8")	
Tool Adaptor Inner Diameter	19.05mm	
Adjustable in height for Max. Stroke	135mm	
Coolant Supply	via tool Holder	
Magnet Power Consumption	85W	
Magnet Adhesion	22540N/2300KGF	
Magnet Dimensions	210MM X 100MM X 64MM	
Weight	23KG	
Hole-Cutting Capacity		
Annular Cutter	Out Diameter	Plate Thickness
	18-60mm	6-75mm
Twist Drill	1-13mm	

# WS-6025MT



## Machine Specification

Voltage (Single Phrase)	100~120V AC 50/60HZ	220~240V AC 50/60HZ
Motor Rated Ampere	20A	10A
Motor Rated Power Consumption	2050W	
No-load Speed	High Speed 730rpm	Dia. 13(1/2")~35mm(1-3/8")
	Low Speed 400rpm	Dia. 36(1-7/16")~60mm(2-3/8")
Tool Adaptor Inner Diameter	19.05mm	
Adjustable in height for Max. Stroke	150mm(without	
Coolant Supply	via tool Holder	
Magnet Power Consumption	85W	
Magnet Adhesion	22540N/2300KGF	
Magnet Dimensions	210MM X 100MM X 64MM	
Weight	26KG	
Hole-Cutting Capacity		
MT3 (Morse Taper) with annular cutter holder	Out Diameter	Plate Thickness
	18-60mm	6-50mm
MT3 (Morse Taper) with drill cutter holder	Jacobs Taper	Drill Chuck Max. Diameter
	JT6	16mm
Twist Drill	Max. Dia. 25mm	
Noss Straight Shank Twist Drill	Shank 1/2", Max. Outer Dia. 16mm	